


## MAILBOXES IN LOWER PAXTON TOWNSHIP

The Board of Supervisors of Lower Paxton Township has established a policy on mailboxes located within the road right-of way and which are damaged as a result of Public Works Department operations. The Township will provide a maximum of fifty dollars (\$50.00) for repair or replacement of a damaged mailbox when:

- a. The mailbox is physically struck by a Township owned and operated truck, snow plow or other equipment.
- b. The mailbox is physically struck by a truck, snow plow or other equipment owned by a subcontractor performing winter maintenance services for the Township.

The Township shall not be responsible and assumes no liability for the repair or replacement of any mailbox that is damaged by snow that is pushed to the edge of road by a snow plow.

The Board of Supervisors recommends that mailboxes be set back no less than 6 inches from the face of curb or edge of pavement to the front face of the mailbox regardless of the circumstances and that mailboxes, including posts, be installed and maintained as follows.



**MAILBOX MUST MEET UNITED STATES POSTAL SERVICE (USPS) STANDARDS AND AASHTO  
ROADSIDE DESIGN GUIDE (11.2.4) (MAILBOX SUPPORT AND ATTACHMENT DESIGN)**